



MONCLA Well Service  
24 hr rig plat



WILL NEED 3 BUNDELS OF RIG UP LUMBER

Location needs to be at least 3 ply mats  
Will also need 3 bundels of rig up lumber